

UNDERWATER BRIDGE INSPECTION REPORT

STRUCTURE NO. 66515

CSAH NO. 1

OVER THE

CANNON RIVER

DISTRICT 6 - RICE COUNTY



PREPARED FOR THE
MINNESOTA DEPARTMENT OF TRANSPORTATION
BY
COLLINS ENGINEERS, INC.
JOB NO. 5221 (CEI 26A)

MINNESOTA DEPARTMENT OF TRANSPORTATION
UNDERWATER BRIDGE INSPECTION

REPORT SUMMARY:

The substructure units inspected at Bridge No. 66515, Piers 1 and 2 and East and West Abutments, were found to be in good to fair condition with no defects of structural significance observed. Light scaling and cracking was observed for the concrete of the substructure units. The channel bottom appeared to be in stable condition with evidence of minor local scour observed at Pier 2.

INSPECTION FINDINGS:


- (A) The concrete was smooth and sound and in good condition with light scaling from the channel bottom to 1.5 feet above the waterline with ¼ inch maximum penetration. There were also random minor cracks on the pier shafts and abutment walls.
- (B) A scour depression 5 feet in radius, 2 feet deep was observed at the upstream end of Pier 2 and along the west face.
- (C) A light accumulation of timber debris consists of 2 inch diameter and smaller branches were observed at the upstream end of Pier 2. There was also a 1 foot diameter log along the west side of Pier 2.

RECOMMENDATIONS:

- (A) Reinspect the submerged substructure units at the normal maximum recommended (NBIS) interval of five (5) years.

I hereby certify that this plan, specification, or report was prepared by me or under my direct supervision and that I am a duly Licensed Professional Engineer under the laws of the State of Minnesota.


Daniel G. Stromberg

A large, stylized handwritten signature in black ink, appearing to read 'Dan G. Stromberg', is written over two horizontal lines.

Date 6/30/2008 Registration No. 21491

Respectfully submitted,

COLLINS ENGINEERS, INC.

A large, stylized handwritten signature in black ink, appearing to read 'Dan G. Stromberg', is written over two horizontal lines.

Daniel G. Stromberg
Registered Professional
Engineer, State of Minnesota

MINNESOTA DEPARTMENT OF TRANSPORTATION
UNDERWATER BRIDGE INSPECTION

1. BRIDGE DATA

Bridge Number: 66515

Feature Crossed: Cannon River

Feature Carried: CSAH No. 1

Location: District 6 - Rice County

Bridge Description: The bridge consists of three spans of multiple steel stringers supporting a reinforced concrete deck. The superstructure is supported by two reinforced concrete abutments and two reinforced concrete hammerhead piers. The piers are numbered from the west end of the bridge.

2. INSPECTION DATA

Professional Engineer/Team Leader: Daniel G. Stromberg, P.E., S.E.

Dive Team: Clayton G. Brookins, Valerie Roustan

Date: October 23, 2007

Weather Conditions: Sunny, 60°F

Underwater Visibility: 1.0 foot

Waterway Velocity: 2.0 f.p.s

3. SUBSTRUCTURE INSPECTION DATA

Substructure Inspected: Piers 1 and 2 and the East and West Abutments.

General Shape: The piers consist of a reinforced concrete shaft supporting a concrete hammerhead cap. The abutments consist of a reinforced concrete breast wall with skewed concrete wingwalls. No design drawings with appropriate footing details were available.

Maximum Water Depth at Substructure Inspected: Approximately 5.0 feet.

4. WATERLINE DATUM

Water Level Reference: The top of the pier cap on the north end of Pier 1.

Water Surface: The waterline was approximately 11.0 feet below reference.
Waterline Elevation = 910.5.

5. NBIS CODING INFORMATION (Minnesota specific codes are used for 92B and 113)

Item 60: Substructure: Code 7

Item 61: Channel and Channel Protection: Code 6

Item 92B: Underwater Inspection: Code B/10/07

Item 113: Scour Critical Bridges: Code 1/91

Bridge is scour critical because abutment or pier foundation is rated as unstable due to observed scour at bridge site.

 Yes X No




Photograph 1. View of Pier 1, Looking Northeast.




Photograph 2. View of Pier 2, Looking North.




Photograph 3. View of West Abutment, Looking Southwest.






UPSTREAM FASCIA PROFILE
Vertical Scale: 1"=20'-0"



DOWNSTREAM FASCIA PROFILE
Vertical Scale: 1"=20'-0"

Note:
Refer to Figure 1 for General Notes.

MINNESOTA DEPARTMENT OF TRANSPORTATION UNDERWATER BRIDGE INSPECTION			
STRUCTURE NO. 66515 OVER THE CANNON RIVER DISTRICT 6, RICE COUNTY UPSTREAM AND DOWNSTREAM FASCIA PROFILES			
Drawn By: PRH	COLLINS ENGINEERS  <small>123 North Wacker Drive Suite 300 Chicago, IL 60606 (312) 704-9300 www.collinsengr.com</small>	Date: OCT., 2007	
Checked By: BAS		Scale: NTS, (U.O.N.)	
Code: 522166515		Figure No.: 2	

MINNESOTA DEPARTMENT OF TRANSPORTATION
OFFICE OF BRIDGES AND STRUCTURES
DAILY DIVING REPORT

INSPECTORS: Collins Engineers, Inc. DATE: October 23, 2007

ON-SITE TEAM LEADER: Daniel G. Stromberg, P.E., S.E.

BRIDGE NO: 66515 WEATHER: Sunny, 60°F

WATERWAY CROSSED: Cannon River

DIVING OPERATION: X SCUBA SURFACE SUPPLIED AIR
 OTHER

PERSONNEL: Clayton G. Brookins, Valerie Roustan

EQUIPMENT: Scuba, Sounding Pole, Lead Line, Probe Rod, Camera, Scraper

TIME IN WATER: 2:50 p.m.

TIME OUT OF WATER: 3:20 p.m.

WATERWAY DATA: VELOCITY 2.0 f.p.s

VISIBILITY 1.0 foot

DEPTH 5.0 feet maximum at Pier 1

ELEMENTS INSPECTED: West and East Abutments and Piers 1 and 2

REMARKS: The concrete was smooth and sound and in good condition with light scaling from the channel bottom to 1.5 feet above the waterline with ¼ inch maximum penetration. There were also minor cracks on the pier shafts and abutment walls. A scour depression 5 feet in radius, 2 feet deep was observed at the upstream end of Pier 2 and along the west face. A light accumulation of timber debris consisting of 2 inch diameter and smaller logs and branches was observed at the upstream end of Pier 2. There was also a 1 foot diameter log along the west side of Pier 2.

FURTHER ACTION NEEDED: YES X NO

Reinspect the submerged substructure units at the normal maximum recommended (NBIS) interval of five (5) years.

MINNESOTA DEPARTMENT OF TRANSPORTATION
OFFICE OF BRIDGES AND STRUCTURES

UNDERWATER INSPECTION CONDITION RATING FORM

BRIDGE NO. 66515
INSPECTORS Collins Engineers, Inc.
ON-SITE TEAM LEADER Daniel G. Stromberg, P.E., S.E.
WATERWAY CROSSED Cannon River

INSPECTION DATE October 23, 2007

NOTE: USE ALL APPLICABLE CONDITION DEFINITIONS AS DEFINED IN THE MINNESOTA RECORDING AND CODING GUIDE INCLUDING GENERAL, SUBSTRUCTURE, CHANNEL AND PROTECTION, AND CULVERTS AND WALL DEFINITIONS TO COMPLETE THIS FORM.

CONDITION RATING

UNIT REFERENCE NO.	UNIT DESCRIPTION	MAXIMUM DEPTH OF WATER	SUBSTRUCTURE						CHANNEL					GENERAL					
			PILING	COLUMNS, SHAFTS, OR FACES*	FOOTINGS	DISPLACEMENT	OTHER	OVERALL SUBSTRUCTURE CONDITION CODE*	SCOUR	EMBANKMENT EROSION	EMBANKMENT PROTECTION	OTHER (DRIFT/DEBRIS)	OVERALL CHANNEL & PROTECTION CONDITION	CONCRETE	STEEL	TIMBER	LOSS OF SECTION	PREVIOUS REPAIR OR MAINTENANCE	OTHER
		1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18
	West Abutment	2.0'	N	7	N	9	N	7	8	7	N	N	7	7	N	N	N	N	N
	Pier 1	5.0'	N	7	N	9	N	7	8	N	N	N	8	7	N	N	N	N	N
	Pier 2	4.0'	N	7	N	9	N	7	6	N	N	7	6	7	N	N	N	N	N
	East Abutment	0.6'	N	7	N	9	N	7	7	7	N	N	7	7	N	N	N	N	N

*UNDERWATER PORTION ONLY

REMARKS: The concrete was smooth and sound and in good condition with light scaling from the channel bottom to 1.5 feet above the waterline with ¼ inch maximum penetration. There were also minor cracks on the pier shafts and abutment walls. A scour depression 5 feet in radius, 2 feet deep was observed at the upstream end of Pier 2 and along the west face. A light accumulation of timber debris consisting of 2 inch diameter and smaller logs and branches was observed at the upstream end of Pier 2. There was also a 1 foot diameter log along the west side of Pier 2.

NOTES: ATTACH SKETCHES AS NEEDED, IDENTIFY REMARK BY REFERRING TO UNIT REFERENCE NO. AND REMARK NO. USE GENERAL SECTION TO IDENTIFY OVERALL PRESENCE OF SPALLS, CRACKS, CORROSION, ETC.